


fixed

casement


fixed



fixed


casement

fixed




double hung

fixed



'fixed'

'double hung'




fixed

fixed

fixed

fixed








Joining Mullion

0° Mullion





St. Matthew's Proposed Window Replacements 2026

Exterior of St. Matthew's Church South Side





Exterior of St. Matthew's Church South Side





Exterior of South Side classrooms and offices



Interior of South Side classrooms and offices



- We do not have air conditioning in this part of the building.
- The reason for changing from a casement to a hung window is that we had to create a makeshift set-up (pictured) to allow us to install temporary A/C units in each divider room
- The frames need to be drilled into the window frames to stay in place. The window sills are now deteriorated and are falling apart.



- This is another view of a different window *without* the wood piece above. The wood piece covers the entire window for two reasons.
- 1. The top portion is open to the elements and eliminates the positive effect of the air conditioning.
- 2. Safety feature to stop entry from the outside.



- By installing hung windows, we can bring hung windows down to the A/C openings while providing security inside the building.



Exterior of St. Matthew's Church, South Side






SW Corner of Building from Parking Lot






West Side of Church





West Side of Church





North Side of Church



North Side of Church



Parking lot view of adjacent middle school to the north.



Parking lot view of United Methodist to the south.



- This is a view of the windows facing the south side classrooms at St. Matthews.
- These are single-hung windows installed in 2004.

Exterior of East High School NE Corner (Wauwatosa Ave)



SE Corner & Across the Street (Wauwatosa AV)



Front View of Church (Wauwatosa AV)



Front View of Church (Wauwatosa AV)

