

# St. Matthew's Proposed Window Replacements 2026



# Exterior of St. Matthew's Church South Side





# Exterior of St. Matthew's Church South Side





# Exterior of South Side classrooms and offices





# Interior of South Side classrooms and offices



- We do not have air conditioning in this part of the building.
- The reason for changing from a casement to a hung window is that we had to create a makeshift set-up (pictured) to allow us to install temporary A/C units in each divider room
- The frames need to be drilled into the window frames to stay in place. The window sills are now deteriorated and are falling apart.





- This is another view of a different window *without* the wood piece above. The wood piece covers the entire window for two reasons.
- 1. The top portion is open to the elements and eliminates the positive effect of the air conditioning.
- 2. Safety feature to stop entry from the outside.





- By installing hung windows, we can bring hung windows down to the A/C openings while providing security inside the building.



# Exterior of St. Matthew's Church, South Side





# SW Corner of Building from Parking Lot





# West Side of Church





# West Side of Church





# North Side of Church





# North Side of Church





Parking lot view of adjacent middle school to the north.





# Parking lot view of United Methodist to the south.



- This is a view of the windows facing the south side classrooms at St. Matthews.
- These are single-hung windows installed in 2004.



# Exterior of East High School NE Corner (Wauwatosa Ave)





# SE Corner & Across the Street (Wauwatosa AV)





# Front View of Church (Wauwatosa AV)





# Front View of Church (Wauwatosa AV)

