

CITY OF WAUWATOSA

7725 W. North Avenue

Wauwatosa, WI 53213

Received by

JUL 21 2023


2:40pm

NOTICE OF CIRCUMSTANCES OF CLAIM

Name:

Marnique Thomason

Address:



Phone:

Email:

Incident/Accident Information

Date: 2/15/23

Time: 10:05

Place: intersection of 92nd
Watertown plank rd.

CIRCUMSTANCES OF CLAIM

In the space below briefly describe the circumstances of your claim. (Attach additional sheets, if necessary.) For auto damages, attach a copy of police report, if any, and a diagram of the accident scene indicating north, south, east or west corners if the accident occurred at an intersection. For bodily injury, indicate nature of injury, whether or not medical attention was given and the name of the treatment provider. Identify any witnesses to the incident/accident.

I was ~~de~~ leaving my apartment and was sitting at the ^{red} light at the intersection of 92nd Watertown Plank Rd heading ^{red} towards Children's hospital. It was a very windy day and a side came from the right side of my car and smacked the driver's side door and went across the hood before continuing down Watertown Plank Rd. I wasn't able to get out to catch the ^{side} sign.

Signed:

Date: 7/10/23

CLAIM

NOTE: You are not required to make a claim at this time. As long as you have filed the above Notice of Circumstances of Claim you may file a claim with the City at any time consistent with the applicable statute of limitations. However, in order for the City to formally accept or deny your claim at this time, the following claim must be completed and signed.

The undersigned hereby makes a claim against the City arising out of the circumstances described above in the amount of \$_____.


To process this claim it is necessary to detail all damages being sought.

Signed: _____

Date: _____

Address: _____







HALL

HALL AUTOMOTIVE AND COLLISION

hallcollision@hallcars.com
 704 BLUEMOUND RD, WAUKESHA, WI 53188
 Phone: (414) 778-1500
 FAX: (414) 778-0539

Workfile ID: 3eadccc4
 PartsShare: 7sDFJf
 Federal ID: 39-1569828

Preliminary Estimate

Customer: THOMPSON, MARNIQUE

Job Number:

Written By: Derek Dertz

Insured: THOMPSON, MARNIQUE
 Type of Loss:
 Point of Impact:

Policy #:
 Date of Loss:

Claim #:
 Days to Repair: 0

Owner:
 THOMPSON, MARNIQUE

Inspection Location:
 HALL AUTOMOTIVE AND COLLISION
 704 BLUEMOUND RD
 WAUKESHA, WI 53188
 Repair Facility
 (414) 778-1500 Business

Insurance Company:

VEHICLE

2023 MAZD 3 Hatchback S Preferred Automatic FWD 4D H/B 4-2.5L Gasoline Gasoline Direct Injection

VIN: [REDACTED]	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color:	Mileage Out:	
State:	Production Date:	Condition:	Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors
 Power Driver Seat
 Memory Package

DECOR

Dual Mirrors
 Tinted Glass
 Console/Storage
 Overhead Console

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Rear Defogger
 Keyless Entry
 Message Center
 Steering Wheel Touch Controls
 Rear Window Wiper
 Telescopic Wheel
 Climate Control
 Remote Starter
 Backup Camera
 Intelligent Cruise

RADIO

AM Radio

FM Radio
 Stereo
 Search/Seek
 Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Hands Free Device
 Rear Side Impact Air Bags
 Blind Spot Detection
 Lane Departure Warning

ROOF

Electric Glass Sunroof

SEATS

Bucket Seats
 Leather Seats
 Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
 Stability Control
 Rear Spoiler
 Signal Integrated Mirrors
 Xenon or L.E.D. Headlamps

Preliminary Estimate

Customer: THOMPSON, MARNIQUE

Job Number:

2023 MAZD 3 Hatchback S Preferred Automatic FWD 4D H/B 4-2.5L Gasoline Gasoline Direct Injection

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT DOOR					
2	Repl	RT Door glass Mazda	BDMT58510B	1	113.79	0.5	
3	Repl	RT Belt molding	BDMT50640C	1	79.39	0.3	
4	*	Rpr RT Door shell (HSS)				<u>6.0</u>	2.0
5		Add for Clear Coat					0.8
6	R&I	RT R&I trim panel				0.5	
7	R&I	RT Handle, outside w/smart keyless black				0.4	
8	*	R&I RT Window regulator				<u>0.5</u>	
9	R&I	RT R&I mirror				0.3	
10		REAR DOOR					
11	Blnd	RT Door shell					1.0
12	R&I	RT R&I trim panel				0.5	
13	R&I	RT Handle, outside black				0.4	
14	*	R&I RT Belt molding				<u>0.3</u>	
15	#	Subl Hazardous waste removal		1	5.00 T		
16	#	Repl Cover Car		1	5.00 T	0.2	
17	#	Color tint / color match		1			0.5
18	#	Repl Corrosion protection primer		1	5.00 T	0.2	
19	#	WET SAND AND BUFF		1		1.3	
20	#	Mask Jambs		1	8.00	0.2	
21	#	Disconnect battery cable		1		0.2	
22		VEHICLE DIAGNOSTICS					
23	*	Rpr Pre-repair scan				m <u>0.5</u> M	
24	*	Rpr Post-repair scan				m <u>0.5</u> M	
SUBTOTALS					216.18	12.8	4.3

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			201.18
Body Labor	11.8 hrs @	\$ 70.00 /hr	826.00
Paint Labor	4.3 hrs @	\$ 70.00 /hr	301.00
Mechanical Labor	1.0 hrs @	\$ 125.00 /hr	125.00
Paint Supplies	4.3 hrs @	\$ 46.00 /hr	197.80
Miscellaneous			15.00
Subtotal			1,665.98
Sales Tax	\$ 1,665.98 @	5.0000 %	83.30
Grand Total			1,749.28