

FEMA Categories	Asset Type	Site #	Location	Description of Damage	Budgetary Estimate (subtotal)	Engineering (10%)	TOTALS
A- Debris Removal	N/A	101	Various	Debris removal in waterways, streets, drainage structures, and around City facilities.	\$ 255,576	\$ -	\$ 255,576
B- Emergency Protective Measures	N/A	102	Various	Search and rescue, policing, emergency pumping, emergency signage, and temporary repairs	\$ 16,295	\$ -	\$ 16,295
	Bridge	107	N. 70th St. over the Menomonee River	Significant erosion in NW corner of bridge. Possible undermining of wingwall in NW corner of bridge.	\$ 53,750	\$ 5,375	\$ 59,125
	Bridge	109	Wisconsin Ave. over Honey Creek	Significant erosion at construction site where bridge is being replaced	\$ 33,000	\$ 3,300	\$ 36,300
	Roadway	110	N. 117th St. and W. Vliet	Buckling of pavement	\$ 50,000	\$ 5,000	\$ 55,000
	Roadway	111	N. 104th St. and W. Concordia Ave.	Buckling of pavement	\$ 44,095	\$ 4,410	\$ 48,505
	Roadway/Parking Lot	112	City lot under Harmonee Ave. Bridge	Significant erosion of parking lot, multi-use path, and bridge piers adjacent to Oak Leaf Trail	\$ 14,500	\$ 1,450	\$ 15,950
	Roadway	113	N. 100th St. and W. Ruby Ave.	Erosion/washout in NW corner of intersection	\$ 26,280	\$ 2,628	\$ 28,908
	Parking Lot/Trails	114	Hart Park	Asphalt pavement washed out and significant erosion	\$ 100,000	\$ 10,000	\$ 110,000
D- Water Control Facilities						\$ -	\$ -
E- Buildings and Equipment	Building	115	Muellner building at Hart Park	Significant flood damage to interior, electrical and mechanical systems, maintenance equipment, and furnishings	\$ 1,105,000	\$ -	\$ 1,105,000
	Building	125	Hart Park Admin Bldg	Minor flood damage to interior, clean up of spaces and equipment replacement	\$ 13,000	\$ -	\$ 13,000
	Building	126	Seed Shed at Hart Park	Minor flood damage to interior, clean up and minimal equipment loss	\$ 6,500	\$ -	\$ 6,500
	Building	127	Storage Shed at northwest side of Hart Park track	Minor flood damage to interior, clean up and minimal equipment loss	\$ 6,500	\$ -	\$ 6,500
	Building	128	Rotary Stage	Cleanup to storage rooms, loss of renters contents in storage rooms	\$ 2,600	\$ -	\$ 2,600
	Vehicles	116	Various	Vehicles and equipment stored in garages	\$ 130,000	\$ -	\$ 130,000
	Building	117	Little Red Store in Village	Significant flood damage to interior, electrical and mechanical systems, furnishings, sidewalks, outside grading	\$ 59,227	\$ 5,923	\$ 65,150
F- Publicly Owned Utilities	Storm Sewer	118	Geralyne Ct storm sewer and outfall	Storm sewer outfalls damaged due to erosion and high flows	\$ 150,000	\$ 15,000	\$ 165,000
	Storm Sewer	130	Railroad bridge outfall	Storm sewer outfall damaged and will need to be replaced	\$ 100,000	\$ 10,000	\$ 110,000
	Storm Sewer	129	103rd St Storm Sewer	Erosion/washout near box culvert connection at back of walk	\$ 25,000	\$ 2,500	\$ 27,500
	Water	119	Under N. 70th Street bridge deck	Insulation and brackets are damaged. Inspection and repair needed.	\$ 50,000	\$ 5,000	\$ 55,000
G- Parks, Recreational, and Other	Park	120	Hart Park	Playground - turf destroyed, needs regrading, portion of asphalt path and curb and gutter damaged.	\$ 150,000	\$ 15,000	\$ 165,000
	Park	121	Hart Park	Football field - complete loss of turf, field facilities, bleachers, and storage units	\$ 1,350,849	\$ 135,085	\$ 1,485,934
	Park	122	Hart Park	Softball - clay infield destroyed	\$ 164,600	\$ 16,460	\$ 181,060
	Park	123	Hart Park	Site furnishings - free standing bleachers, picnic tables, garbage cans, storage boxes, and other furnishings	\$ 65,850	\$ -	\$ 65,850
	Park	124	Hart Park	Volleyball courts - material washed out	\$ 5,000	\$ 500	\$ 5,500
TOTALS					\$ 3,977,622	\$ 237,630	\$ 4,215,253