To: Wauwatosa building department

From: Megan and Shawn Slattery 2320 N 69th St Wauwatosa, Wi 53213

We recently moved from Las Vegas, NV to our current home in Wauwatosa due to matching at MCW for residency. As soon as we walked through the cute neighborhood streets we knew this is where we wanted to be. We immediately fell in love with the area. We had also heard great things about the school system and the city in general.

We knew when we purchased the home, we would want to create some extra useable space in the basement to accommodate our growing family.

It never occurred to us, our realtor, or our home inspector that there would be a problem with that plan.

Now we have been made aware that our stairs are not code compliant, and as a result, our permit to create a rec room in the basement has been denied.

Although there is no way possible to rebuild the stairs to make them code compliant, we are willing to do what it takes to make sure the space is both safe, and comfortable for our family.


As a side note, the stairs that lead to the second floor have the same issues making them non-compliant as well. Someone allowed the second floor to be finished, so we are confident that you will let us know what steps we need to take in order to get a variance to continue with the rec room project.


We understand that the stair issue creates a problem for firefighters in full gear to get to the basement in the event that it becomes necessary.


To offset that issue, we are willing to have an egress window and well installed as a better means of ingress/egress in case of emergency. We are also planning to put fire extinguishers in the rec room, laundry room, and storage area in the basement.

If there are other steps we should be considering, please let us know so that we can make a plan to comply.


Thank you for your assistance.







h Buch 15 16 17 19 20 21 22 Job # 22 50 51 52 53 54 55 56 57 11/2! **Client Name** WINDOW A 32" Ø 32" (/ PPV Date & Time 00 Walu NM 10 1:00pm 24 Q'5" 0 4114 11 Firished HElastric cleurest. 12 **Preferred Install Date** an Thisside P 13 F Pant 14 20'6" 14% 15 60 7'41 Front LF - 6-23-13 16 Q 17 32" (WH 0 42 18 0 4' Ø 9 19 10' LF 20 Q -0-4-15-0-8-10 21 × 32 " \$ \$-47 22 6 D 0 23 D LF 24 Ъ 25 W R Q SINK W A 26 -27 WINDOW 22'9" 1 7 21 K WINDOW 28 Joist \underline{D}_{uct} IBeam 29 Paint Ceiling Black) 63" 6'3" 30 CLOAN STORAGE/BONNS 611 31 Door to 32 Tread Riser Step Onts 16e 5Pace 377 # 33 6'7" 34 10" Q^{n} 35 Q OUTLATS 10-36 Approach W_{idth} Pecanflants 37 3 \$ Switch / Dimutr 38 +1- 377 \$ 39 2 @ Smoke or Smoke 40 40 41 Window 1 2'9x 1'8" 42 3 -B- ntility Lights 43 Z'9ªx 44 Window 2 9 CAN Lights 45 Ø 46 'Sr <u>N</u>-47 E EXHAUST FAN Min 75 LFM - VENTED by Others L×4: 24 49





MEGAN AND SHAWN SLATTERY 2320 N 69TH ST WAUWATOSA, WI 53213 702-540-6737

BUILDING DEPT-APPLY ON LINE

VINYL COVERED EVERLAST INSULATED PERIMETER WALL	42 LF

VINYL COVERED EVERLAST NON-INSULATED WALL WITH METAL STUDS 47 LF

VINYL COVERED EVERLAST NON-INSULATED WALL WITH NO STUDS

ALL TRIM TO BE WHITE, PRE-FINISHED, VINYL

DOORS-6 PANEL, HOLLOW, PRE-HUNG, WHITE WITH SATIN NICKEL _LEVERS____

FLOORING-APPROX 377 SQ FT PECAN PLANKS

CEILING-PAINT BLACK APPROX 377 SQ FT

SOFFITS-NONE

HVAC-HOMEOWNER IS RESPONSIBLE FOR PROVIDING HEAT AND VENTILATION AS REQUIRED BY CODE, INCLUDING FRESH AIR INTAKE AND VENTING FAN TO THE OUTSIDE

ELECTRIC WORK-CIRCUITS AS NECESSARY, 2 SMOKE OR SMOKE/CO DETECTORS, 10 OUTLETS, 3 SWITCH/DIMMER, 3 UTILITY LIGHTS, 9 CAN LIGHTS, 1 EXHAUST FAN WITH OCCUPANCY SENSOR (MIN 75 CFM)

ADDITIONAL ITEMS-ACCESS PANELS AS NEEDED, INSTALL EGRESS WINDOW AND WELL-4'X4' DOUBLE SLIDING VINYL WINDOW WITH MOLDED FIBERGLASS WELL AND LADDER, PROVIDE 4 FIRE EXTINGUISHERS, ONE FOR EACH OF THE BASEMENT AREAS

*ALL DIMENSIONS ARE APPROXIMATE AND ARE SUBJECT TO CHANGE BASED ON AS-BUILT CONDITIONS