W98009 Honey Creek Damage

August 9-10, 2025



Agenda:

- 1. Honey Creek at Honey Creek Parkway
 Bridge at St. Anne Ct, City of Wauwatosa
- 2. Honey Creek at W. Blue Mound Road Bridge, City of Wauwatosa/Milwaukee



Honey Creek Pkwy Bridge at St. Anne Ct: in stream

channel under SE corner of bridge, facing W downstream



Honey Creek Pkwy Bridge at St. Anne Ct: in stream

channel under SE corner of bridge, facing W downstream






Honey Creek Pkwy Bridge at St. Anne Ct: in stream

channel under SE corner of bridge, facing E upstream



Honey Creek Pkwy Bridge at St. Anne Ct: sw bridge

approach, 6" and 24" stormsewer and apron to stream channel







Honey Creek Pkwy Bridge at St. Anne Ct: anticipated

construction repair areas (red boxes)

A: replace missing and displaced concrete channel

B: replace displaced concrete, remove debris, rock reinforcement

C: stabilize undercut sewers







Milwaukee Metropolitan Sewerage District

W. Blue Mound Road Bridge: facing SE upstream toward Blue Mound Rd.





W. Blue Mound Road Bridge: facing downstream from S.

bridge abutment, NW toward St. Anne Ct





W. Blue Mound Road Bridge: from S. stream bank, facing

N. towards St. Anne Ct; 50' DS from bridge





W. Blue Mound Road Bridge: anticipated construction repair areas (red boxes)

A: access

B: concrete channel reinforcement, reshape and stabilize N. embankment, rock reinforcement

C: remove debris field





